



National Association of Chimney Engineers

PO Box 849, Metheringham, Lincoln, LN4 3WU, UK

Tel: 01526 322555
(+44 1526 322555)
Email: info@nace.org.uk

Fax: 01526 888007
(+44 1526 888007)
<http://www.nace.org.uk>

CHIMNEYS, COMBUSTION APPLIANCE AND SMOKE NUISANCE

SEMINAR

SAMPLE EVIDENCE OF DEFECTIVE WORKMANSHIP



904 GRADE LINER AFTER 3 MONTHS USE



**BITUMINIOUS MATERIAL REMOVED
FROM INSPECTION PLATE**



CONSERVATORY FIRE RISK



TWIN WALL INSTALLATION TO A CONSERVATORY (FIRE HAZARD)



FIRE RISK IN FLUE CHAMBER



FURTHER FAILURE OF 904 LINER (1)



**INCORRECT FITTING OF
CONNECTING FLUE SECTIONS**



NON COMPLIANT FLUE CONNECTION



ROTTED TOP PLATE AFTER 3 MONTHS USE



VITREOUS CONNECTING FLUE READY FOR USE



ASBESTOS CLAMPED TO PLASTERBOARD CLOSURE PLATE



DANGEROUS TERMINATION OF CONNECTING FLUE



DEFECTIVE CHIMNEY



DEFECTIVE INSTALATION – NO THERMAL SPACING




DIRECT FIRE RISK TO SUPPORTING TIMBER BEAM



FURTHER FAILURE OF 904 LINER (2)



FURTHER FAILURE OF 904 LINER (3)



LIVE CABLES ADJACENT TO TWIN WALL CHINEY SYSTEM (1)



LIVE CABLES ADJACENT TO TWIN WALL CHINEY SYSTEM (2)



REMOVAL OF 2.NO MASONRY FLUE SHAFTS IN ROOF SPACE